

<b>Search Notes</b>	Application/Control No.	Applicant(s)/Patent Under Reexamination
	110622287	SAXENA, RAHUL
Examiner	Art Unit	
	Hussain, Tauqir	2452

<b>SEARCHED</b>			
<b>Class</b>	<b>Subclass</b>	<b>Date</b>	<b>Examiner</b>
709	236,238,246	03/26/2007	TH
370	254,404,395,53	03/26/2007	TH
370	389,392,393,462	03/26/2007	TH
Above	Search Updated please see attached search note	03/26/2007	TH
Above	Search updated	11/20/2008	TH
Above	Search updated	06/01/2009	TH
Above	Search Updated	1/8/2010	TH

<b>SEARCH NOTES</b>			
<b>Search Notes</b>	<b>Date</b>	<b>Examiner</b>	
frame same buffer same (switch router brouter bridge)	03/26/2007	TH	
memory same frame same buffer	03/26/2007	TH	
(memory same frame same buffer same (switch router brouter bridge))	03/26/2007	TH	
(port\$1 interface) same (v\$1lan tag\$1 label\$1 vlan)	03/26/2007	TH	
frame same buffer same (switch router bridge)	03/26/2007	TH	
(update updating swap swapping remov\$3 insert\$3) same (tag header "vlan tag")	03/26/2007	TH	
(vlan v\$1lan) same (remov\$3 updat\$3 add\$3 insert\$3) same (tag header label)	03/26/2007	TH	
Above search updated, please see attached search note	03/26/2007	TH	
Please see attached search note	11/20/2008	TH	
Please see attached search note	06/01/2009	TH	
Please see attached search note	1/8/2010	TH	

<b>INTERFERENCE SEARCH</b>			
<b>Class</b>	<b>Subclass</b>	<b>Date</b>	<b>Examiner</b>
709	236,238,246	03/26/2007	TH
709	((insert\$3 strip\$4 generat\$3) adj (CRC VLAN) with (second transmit output) adj port same frame).clm.	06/01/2009	TH
	Above Search Updated	1/8/2010	TH